



# CAUTION



## Horizontal Milling Machine

- Keep work area clean.
- Securely clamp workpiece to table.
- Use spring-loaded operational handles with power-fed tables.
- Cover and store all unused cutters.

Note: Immediately report all machinery malfunctions to the supervisor.