



CAUTION



Knee Mill Milling Machine

- Keep work area clean.
- Before you begin:
 - Securely clamp workpiece to table.
 - Use spring-loaded operating handles on power-fed work table.
 - Use barrier guards when conducting fly cutting operations.
- Cover and store all unused cutters.

Note: Immediately report all machinery malfunctions to the supervisor.