



# CAUTION



## Vertical Milling Machine

- Keep work area clean.
- Before you begin:
  - Securely clamp workpiece to table.
  - Use spring-loaded operating handles on power-fed worktables.
  - Use barrier guards when conducting fly cutting operations.
- Cover and store all unused cutters.

Note: Immediately report all machinery malfunctions to the supervisor.