



CAUTION



Wood Surfacer or Planer

- Keep work area clean.
- Be sure available dust collection system is operating.
- Before you begin:
 - Inspect workpiece for nails, screws, knots, etc.
 - Check cutter height adjustment.
- Never stand directly behind work.
- Do not remove excessive amounts of material at one time.
- Do not work material too small for machine.

Note: Immediately report all machinery malfunctions to the supervisor.