



# CAUTION



## Abrasive Metal Cutting Chop Saw

- Keep work area and abrasive surfaces clean.
- Be sure available dust collection system is operating.
- Before you begin:
  - Replace or repair sticky spring-loaded trigger switches.
  - Replace dull, cracked or fouled saw discs.
  - Use proper discs to cut material.
  - Securely clamp workpiece.
- Never clamp or wedge guard in open position.

Note: Immediately report all machinery malfunctions to the supervisor.