



CAUTION



Drop Hammer

- Keep work area clean.
- Secure all overhead machinery parts.
- Use hand tools to feed workpiece.

Note: Immediately report all machinery malfunctions to the supervisor.