



CAUTION



Metal Working Lathe

- Keep work area clean.
- Before you begin:
 - Be sure all personnel are clear of chuck before operation.
 - Check operating speed.
- Do not work material too small for machine.
- Securely clamp workpiece.
- Store unused tools and chucks in racks.

Note: Immediately report all machinery malfunctions to the supervisor.