



# CAUTION



## Multiple Spindle “Gang” Drill Press

- Keep work area clean.
- Before you begin:
  - Replace dull or damaged drill bits.
  - Use clamps, vises, etc., to secure workpiece to table.
- Do not grab quick-change chucks while rotating, regardless of speed.

Note: Immediately report all machinery malfunctions to the supervisor.