



CAUTION



Spindle Sander

- Keep work area clean.
- Be sure available dust collection system is operating.
- Use proper sanding drum size and grit for work piece.
- Do not mix metal and wood dusts
- Before you begin:
 - Inspect workpiece for nails, screws, knots, etc.
 - Be sure filler plate/drum gap is no more than 1/8”.
 - Inspect sanding drum for defects.
 - Clean sanding drum properly
 - Adjust guard to cover unused part of drum

Note: Immediately report all machinery malfunctions to the supervisor.