



# CAUTION



## Wood Working Lathe

- Keep work area clean.
- Before you begin:
  - Inspect workpiece for nails, screws, knots, etc.
  - Check operating speed.
- Do not work material too small for machine.
- Do not use broken chisels and gouges.
- Store unused chisels and gouges in tool racks.

Note: Immediately report all machinery malfunctions to the supervisor.